

57357

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

① Manifest Number **015-001536**

SFUND RECORDS CTR
999000885

GENERATOR (Generator Must Complete)

ALUMINUM COMPANY OF AMERICA

② Name **VERNON WORKS**EPA NO. **CAD074126687**Address **5151 Alcoa Ave.** Phone No. **588-6141**City, State, Zip **Vernon, Ca. 90058**

③ Designated TSD Facility (Authorized to operate under an approved state program or federal program)

Name **OPERATING INDUSTRIES, INC.**EPA NO. **CAD080012024**Address **900 N. Potrero Grande Dr.**City, State, Zip **Monterey Park, Ca.**

④ Alternate TSD Facility

Name **CHEMICAL WASTE MANAGEMENT INC.**EPA NO. **CAT000646117**Address **P.O. Box 1104, 430 W. Elm Ave.**City, State, Zip **Coalinga, Ca. 93210**

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE				
WASTE				

CONTAINERS NUMBER: _____

TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS
☐ TANK TRUCK ☐ DUMP TRUCK
☐ OTHER

⑥ WASTE CATEGORY **#7**

⑦ EX. HAZ. WASTE PERMIT NO. _____

⑧ GENERATING PROCESS **Aluminum Fabrication**

LIST COMPONENTS:

CONC.
UPPERRANGE
LOWER

UNITS

CONC.
UPPERRANGE
LOWER

UNITS

⑨ A. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.	E. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.
B. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.	F. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.
C. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.	G. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.
D. _____	_____	_____	<input type="checkbox"/> % <input type="checkbox"/> ppm.	Non Hazardous Material 100 %			

⑩ WASTE PROPERTIES: pH **7** ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen⑪ PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☒ Other **Aluminum Oxides & Water**⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other _____

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL
RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

⑬

Signature of Authorized Agent and Title

Date Shipped **4-10-81****TRANSPORTER** (HAULER MUST COMPLETE)⑭ NAME **ASBURY OIL CO.**EPA NO. **CAD028277036**ADDRESS **13419 Halldale Avenue** PHONE NO. **(213) 321-1392**CITY, STATE, ZIP **Gardena, California 90249**⑮ PICK-UP DATE **4-10-81**
TIME **8:30** AM ☐ PM

⑯

Signature of Authorized Agent and Title

Date **4-10-81****TSD FACILITY** (FACILITY-OPERATOR MUST COMPLETE)⑰ NAME **OPERATING INDUSTRIES, INC.** ⑱ QUANTITY (If Measured) _____EPA NO. **CAT080012024** ⑲ STATE FEE (If Any) _____

PHONE NO. _____

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT: _____

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY: _____

㉒ NAME _____

EPA NO. _____

㉓

Signature of Authorized Agent and Title

Date Accepted **4-10-81**

ORIGINAL